

Name: POLYTECH jacket	Code: MC5714Q5	MC57 CLOTHING - POLYTECH SERIES
------------------------------	-----------------------	--

Description

Jacket in 75% cotton, 24% polyester, 1% antistatic fibre fabric, weight 280 g/m². It features a Chinese collar with Velcro for neckprotection, concealed front zipper closure with metal snap buttons, two chest pockets and two low pockets with flaps and Velcro, elastic cuffs, reflective piping on the chest.

THE JACKET SHALL BE WORN IN COMBINATION WITH THE BIB-TROUSERS OR TROUSERS.

- The Polytech series is made with a multi-purpose fabric that combines antistatic properties with resistance to flames, heat and chemical products.
- Thanks to its features it is multi-purpose, practical and resistant, breathable and comfortable.

The product is designed and manufactured to comply with the requirements of Regulation (EU) 2016/425 and subsequent amendments.

In combination with the jacket it is possible to wear our under garments: Carboflame undershirt art. MC5610 and Carboflame underpants art. MC5620, meeting the point A.2 of IEC 61482-2 which is stating that the electric arc protective clothing shall be used with under garments made of materials that would not melt with the arc.

GIVEN THE CURRENT MIXED STOCK, IT IS POSSIBLE THAT THIS ITEM WILL BE DELIVERED WITH THE RESTYLED VERSION (AS SHOWN IN PHOTO) AND FORMER VERSION.

The OEKO-TEX® certificate of the main outer fabric is under review.



Category III	Colours DARK BLUE	Available Sizes Made to order: 38 - 38, 66 - 70 In stock: 44 - 64
Quantity/Carton	EC Standards	Important Information

20

EN 1149-5



EN ISO 11611



Class:1
Values:A1

EN ISO 11612



Limited Flame Spread:A1
Convective Heat:B1
Radiant Heat:C1
Molten Iron Splashes:E3
Contact Heat:F1

EN 13034



Type:6

CEI EN 61482-2



APC:1
ATPV (Fabric):11 cal/cm²
ELIM (Fabric):10 cal/cm²

Petrochemical Industry, Metalworking Industry, Refining Industry, Chemical Industry, Industrial Maintenance and Assemblies, Gas, Water and Electricity Mains Maintenance and Management, Oil & Gas industry.

Keep in a cool dry place, far from heat sources and direct light.

Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.

We recommend to follow the washing instructions. Wash separately from other types of garments to avoid the transfer of inflammable fibres.

Dexterity

Storage and cleaning

